

Honeywell 500PSI Gauge MIP Series Pressure Sensor P/N H-PS500G-HMIP

Drawing Revision 1 - 30/4/21



www.youtube.com/efihardware



info@efihardware.com



www.facebook.com/efihardware

www.efihardware.com




(03) 9873 5400 +613 9873 5400



(03) 9873 5955 +613 9873 5955

Pressure Vs Voltage




0PSI Gauge (Atmospheric Pressure)

500PSI Gauge (500PSI Above Atmospheric Pressure)

NOTES:

Gauge Pressure is pressure above atmospheric pressure. You might also think of it as "positive" pressure".

This is an active sensor. Do not use a pull-up resistor on the signal of this sensor. The output is driven to the correct voltage by the electronics inside the sensor.



APPLICATIONS:

This sensor is most often used to monitor transmission pressure.

This sensor has a stainless steel body.